# INSPECTION REPORT

















## Cabin

**Condition** 

1. Seat	Excellent
2. Switches	Excellent
3. Dashboard	Excellent
4. A/C & Heating System	Excellent
5. Cabin Doors	Excellent
6. Windows	Excellent
7. Wipers	Excellent
8. Flooring	Excellent

9. Other

**Inspection Point** 

Minor scuffing on interior surfaces

Comment

## Engine

Inspection Point	Condition	Comment
1. Alternator	Excellent	
2. Leakages	Excellent	
3. Oil condition	Excellent	
4. Exhaust	Excellent	
5. Fluids level	Excellent	
6. Cooling system	Excellent	

Excellent

Excellent

7. Belts

8. Noise

9. Other





#### **Exterior**

**Condition** 

Comment

Minor scratches and scuffs present

**Inspection Point** 

8. Other

8. Other

1. Chassis	Excellent
2. Paintwork	Excellent
3. Lights	Excellent
4. Steps & Rails	Excellent
5. Corrosion	Excellent
6. Cleanliness	Excellent
7. Damages	Excellent

## Powertrain

Inspection Point	Condition	Comment
1. Axles	Excellent	
2. Joints	Excellent	
3. Oil condition	Excellent	
4. Brakes	Excellent	
5. Gearbox	Excellent	
6. Differentials	Excellent	
7. Suspension	Excellent	





## **Hydraulics**

**Condition** 

Comment

**Inspection Point** 

8. Other

•	
1. Hoses & Lines	Excellent
2. Steering	Excellent
3. Pumps	Excellent
4. Cylinders	Excellent
5. Corrosion	Excellent
6. Fluid levels	Excellent
7. Other	

## **Testing**

Inspection Point	Condition	Comment
1. Transmission test	Excellent	
2. Engine test	Excellent	
3. Steering test	Excellent	
4. Electrics test	Excellent	
5. Braking test	Excellent	
6. Power test	Excellent	
7. Suspension test	Excellent	





#### **Undercarriage**

Inspection Point	Condition	Comment
1. Rollers	Excellent	
2. Idlers	Excellent	
3. Sprockets	Excellent	
4. Links	Excellent	
5. Bushings	Excellent	
6. Carriers	Excellent	
7. Shoes	Excellent	
8. Other		

#### **Conclusion**

#### **Inspection's comment**

The Komatsu PC1250SP-11, manufactured in 2023 with just 419 operational hours, is in outstanding condition, reflecting its limited use and careful maintenance. This inspection reveals no significant issues, particularly with the hydraulic system and undercarriage, which are both in optimal condition.

Operational Hours and General Condition: The excavator shows minimal signs of use, consistent with its low operational hours. It has been maintained excellently, with no significant wear visible.

Bucket and Attachment Points: The bucket and attachment points show minimal wear. The bucket teeth are in very good condition, indicative of the light use and careful operation of the machine.

Engine and Powertrain: Both the engine and powertrain are functioning flawlessly, with no superficial wear that impacts performance. The machine operates smoothly, with all systems performing at their expected capacity. Cabin and Controls: Inside, the cabin is pristine, with all controls in perfect working order. Minor scuffing on interior surfaces does not detract from the overall excellent condition of the cabin.

Exterior Condition: The paint and bodywork maintain a like-new appearance, with only minor scratches and scuffs present, typical of light operational use.

Overall Assessment: The Komatsu PC1250SP-11 stands as a nearly new machine, showcasing exceptional care and minimal use. Its excellent condition across all aspects makes it a prime choice for demanding excavation tasks.

Recommendations: Given its excellent condition, the Komatsu PC1250SP-11 is ready for immediate deployment in any project requiring a high-performance excavator. Continued adherence to routine maintenance schedules will ensure its longevity and reliability.

This inspection confirms the Komatsu PC1250SP-11 as a superior selection for those seeking a powerful, dependable excavator with virtually no wear and tear, ready to contribute to any operation's success.



